

Photos



Photo 1 – Subject site and adjacent properties as seen from across S. Ashland Ave. looking west. Subject buildings identified by address. Photo courtesy of Cook County Assessor’s Office.

Photos



Photo 2 – Close up of 2012 S. Ashland Ave. with 2010 S. Ashland Ave. garage structure in the background and 2008 S. Ashland Ave. vacant lot in the foreground. Facing west. Photo courtesy of CDM Smith, Inc.



Photo 3 – Southeast corner of 2012 S. Ashland Ave. facing northwest along S. Ashland Ave. Photo courtesy of CDM Smith, Inc.

Photos



Photo 4 – Northeast corner of 2012 S. Ashland Ave. facing south west along S. Ashland Ave. Photo courtesy of CDM Smith, Inc.



Photo 5 – View of the northern side of 2012 S. Ashland Ave. and the adjoining, single-story structure interconnected to 2010 S. Ashland Ave. Facing southwest. Photo courtesy of GSG Consultants, Inc.

Photos



Photo 6 – View of 2010 S. Ashland Ave. garage structure facing west. Photo courtesy of The Resurrection Project.

Photos



Photo 7 - Rear of 2010 S. Ashland Ave. garage structure along the alley, looking southeast from W. Cullerton St. Photo courtesy of CDM Smith, Inc.



Photo 8 – Rear of 2010 S. Ashland Ave. garage structure along the alley, facing east. Photo courtesy of CDM Smith, Inc.

Photos



Photo 9 - View of the main corridor running east to west through the building. Photo taken facing west. Photo courtesy of GSG Consultants, Inc.



Photo 10 - View of one of the rooms on the east side of the main floor, previously utilized as an examination room. Photo taken facing southwest. Photo courtesy of GSG Consultants, Inc.

Photos



Photo 11 - View of one of the rooms on the north side of the main floor, currently being utilized as an office, facing northwest. Photo courtesy of GSG Consultants, Inc.



Photo 12 - View of the western most room on the main floor of the building with entry points to the basement, second floor and the second building on site, photo taken facing west. Photo courtesy of GSG Consultants, Inc.

Photos



Photo 13 – View of the basement, facing east. Photo courtesy of GSG Consultants, Inc.



Photo 14 - View of the northwest corner of the basement, facing west. Photo courtesy of GSG Consultants, Inc.

Photos



Photo 15 – View of the westernmost room on the second floor, facing east. Photo courtesy of GSG Consultants, Inc.



Photo 16 – View of the westernmost room on the second floor, facing west. Photo courtesy of GSG Consultants, Inc.

Photos



Photo 17 – Easternmost room on the second floor, facing southeast. Photo courtesy of GSG Consultants, Inc.



Photo 18 - Section of the second-floor ceiling, showing significant disrepair. Photo courtesy of GSG Consultants, Inc.

Photos



Photo 19 – Easternmost room in the second building, facing southwest. Photo courtesy of GSG Consultants, Inc.



Photo 20 – Southernmost room in the second building, facing southwest. Photo courtesy of GSG Consultants, Inc.

Photos



Photo 21 – Southernmost room on the second floor of the second building, facing east. Photo courtesy of GSG Consultants, Inc.



Photo 22 – Room situated on the east side of the second floor of the second building, facing northeast. Photo courtesy of GSG consultants, Inc.

Photos



Photo 23 – Main floor of the garage (2010 S. Ashland Ave.) facing northwest. Photo courtesy of GSG Consultants, Inc.



Photo 24 – Main floor of the garage facing northeast. Photo courtesy of GSG consultants, Inc.

Photos



Photo 25 – Main floor of the garage facing southeast. Photo courtesy of GSG Consultants, Inc.



Photo 26 – Second floor of the garage facing north. Photo courtesy of GSG Consultants, Inc.

Photos



Photo 27 – Second floor of the garage facing southwest. Photo courtesy of GSG Consultants, Inc.